


Parts needed to mount the KOZUS extrusion



Tools needed for mounting:

- mounting glue

WARNING! All LED tapes should be connected to 12 V or 24 V power supplier, depending on the LED tape.

IMPORTANT: Instruction presensts most basic form of montage. For more information visit www.klusdesign.com



