

Parts needed to mount the PIKO profile



Extrusion (A)



End caps (B)



Cover (C)




LED strip (D)

WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly.
More methods and related accessories can be found at www.klusdesign.eu/uk

1. Mount the LED strip (D), insert the cover (C), and then insert the end cap (B). Run the cable to the power source.



2. Apply double-sided tape to the extrusion (A), and attach the extrusion to the surface. Connect power.

